



① CYNLLUN LLEOLIAD / LOCATION PLAN  
1:2000



**Cynllunio**

Derbyn 07.11.23

No. Description Date  
DO NOT SCALE FROM DRAWING  
CHECK ALL DIMENSIONS ON SITE

**OUTLINE**  
BUILDING SOLUTIONS  
*Cyf*

Tel: 07584 570479  
E-mail: info@obosol.co.uk



CPD Talycaen Cells  
Gloeddia Gla, Talycaen,  
Gwynedd, LL54 6BY

Cynllunio Uroliad  
Location Plans

Drawn by: GU Date: Hyd 2023  
Drawing No: Rev  
065-2023-056 GA001





#### Biodiversity Enhancements

The following enhancements / mitigation measures have been taken from the Preliminary Ecological Assessment (PEA). Reptile Survey Report and Bird Survey Report as prepared by Bellot Moorsley.

#### Recommendations from PEA


- Following the preliminary ecological bat survey it is recommended that emergence surveys take place on the north and western side of the changing rooms. See attached survey results.
- The open mosaic habitat of previously developed land is listed as 'scattered' habitat. Loss of the open mosaic habitat of previously developed land will result in the loss of habitat for the species listed above. A buffer zone should be placed on the northern and southern boundary of the new football field along with a front of slate to provide habitat for various invertebrates.
- This habitat from the area of the open mosaic habitat should be retained and used in the state bunt on the site's boundary. This will ensure that any new stock is retained.
- No machinery or equipment should be stored on the site even so all machinery, equipment and boats should be cleaned and sprayed with 'viscon' disinfectant before entering and leaving site to stop the introduction of invasive non-native species and suitable excavated material can be reused on site.
- Any excavations should leave a minimal ladder or larched back slates to allow access.
- The proposed new bog garden should be removed as a tree remaining trees between the existing football pitch and proposed football pitch will be lost (new species list in table 10). These were relatively young in age and any trees lost will be replaced by the planting of additional trees.
- The ecologist will check the trees and scrub for nesting birds immediately before the works start if within the bird nesting season (March to August) individual nest needs are found the works will be postponed until the birds have fledged. All machinery and equipment should be stored on the site to prevent damage to vegetation for invertebrates and any common roosts found on site will also be moved to this location.
- The proposed new hedge should be planted in the area of the state bunt and vegetation on the site boundary to provide invertebrates such as butterflies or moths habitat to complete their life cycle.
- Rooflights should be removed from the proposed new storage shed to prevent damage to vegetation for invertebrates.
- If rooflights are included on site in the future a HRA to identify if the proposal is likely to have a significant effect on LHS bank of Glyndwr SAC must be completed.
- The proposed new hedge and other proposals identified is likely to have much less of an ecological impact than the current permitted development rights for the site under planning ref CBA/0474/22L.

#### Recommendations from the RRP Report

- Vegetation clearance should be undertaken in stages; stage 1 to clear to 20cm height, stage 2 to clear the remaining vegetation the following day to enable the reptiles time to relocate from the area.
- All machinery and equipment including staff boats should be cleaned and washed before entering and leaving the area of the works to stop the introduction or movement of invasive non-native species in the area of the works.
- If there is any evidence of dormouse activity (e.g. tracks or droppings) then the use of this area must be avoided until the determination of the building, a repeat survey needs to be carried out.
- There should be opportunities for bats and birds along the existing boundaries.
- A corridor for nesting birds will be completed before the works start of within the bird breeding season generally 1<sup>st</sup> March to 31<sup>st</sup> August.
- Bats are highly mobile animals and can move into a property at any time during a survey has taken place, in the unlikely event that a bat is found during the works, or there may be any other disturbance to the roosting behaviour, call the bat expert (no impacts are expected on the changing room building now a roosting bat is presumed to be currently in the constituency).

#### Recommendations from the Bat Report

- Two integrated bat swift boxes should be included in the new building and located on the north facing wall.
- Exclusion mesh should be applied to the windows of the proposed bat roost on the north facing wall.
- All machinery equipment including staff boats will be cleaned and washed before entering and leaving the area of the works to stop the introduction or movement of invasive non-native species in the area of the works.
- If there is any evidence of dormouse activity (e.g. tracks or droppings) then the use of this area must be avoided until the determination of the building, a repeat survey needs to be carried out.
- There should be opportunities for bats and birds along the existing boundaries.
- A corridor for nesting birds will be completed before the works start of within the bird breeding season generally 1<sup>st</sup> March to 31<sup>st</sup> August.
- Bats are highly mobile animals and can move into a property at any time during a survey has taken place, in the unlikely event that a bat is found during the works, or there may be any other disturbance to the roosting behaviour, call the bat expert (no impacts are expected on the changing room building now a roosting bat is presumed to be currently in the constituency).



Gweler Cynllun Diwygiadig  
See Amended Plan

#### Parking

Currently the majority of the people who attend the club park in the public car parks of Glynllifon Talybont which is located on the opposite side of the road.

The formation of a new pitch merely pitch during winter months and services the existing number of visitors. The pitch is not used by teams as staggers and play at different times of the year. Therefore there is never going to be a situation where all youth and senior teams are using the pitch at the same time resulting in a need for a large amount of parking space.

Additional parking provision is to be formed with stone walls which will allow and surface water to penetrate through into the substrate.

B	Biodiversity notes added	Aug '23
A	Additional notes on parking added	Rugby '23
No	Date	Date
DO NOT SCALE FROM DRAWING		
CHECK ALL DIMENSIONS ON SITE		

OUTLINE  
BUILDING SOLUTIONS  
Cym



CPD Talybont Cells  
Glyndwr Gla, Talybont,  
Gwynedd, LL54 6BY


Cymru Safle Arfaethdiga  
Proposed Block Plan

Drawn by: GL	Date: Hyd 2023
Drawn No:	Rev:
065 2023-056 GA002	B

Citation ISO Certification  
Quality management ISO 9001:2015

Certificate No: 00000000000000000000000000000000

**Proposed Materials:**  
Walls - Green box profile cladding  
Roof - Green box profile cladding  
Windows & Doors - Steel







**Cynllunio**  
Derbyn 04.12.23

**GWYBODAETH YCHWANEGOL  
ADDITIONAL INFORMATION**



② DRYCHIAD 3D ARFAETHEDIG / PROPOSED 3D VIEW



A Position of existing changing room as per  
No Description  
Date  
DO NOT SCALE FROM DRAWING  
CHECK ALL DIMENSIONS ON SITE

**OUTLINE**  
BUILDING SOLUTIONS  
Cym

Tel: 01584 570879  
Email: info@obosuf.co.uk



CPD Talybont Cells  
Gloeddia Glan, Talybont,  
Gwynedd, LL54 6BY

Sied Arfaethedig  
Proposed Shed

Drawn by: GU Date: 04/23  
Drawing No: 065-2023-056 GA003 Rev: A

Citation ISO Certification  
Quality management ISO 9001:2015  
Certificate No: 00052021





